

1

2

3

4

5

6

A

B

C

D

E

F

Touchscreen control panel

PNEUMATIC CABINET Regulator set to 6 BAR

Blade lubricant tank with filling port and level indication

DANGER AREA
ELECTRICAL CABINET
400V, 3 Phase, 50Hz
Neutral & earth

DANGER AREA
Exit Guard

Pneumatic controls:
Clamp Pressure
Saw raise/lower speed

DANGER AREA
Saw Blade / Product Clamp

DANGER AREA
Inlet Guard

Swarf extraction boss, \varnothing 100mm



Gillard Cutting Technology
Alexandra Way
Ashchurch Business Centre
Tewkesbury,
Glos. GL20 8NB
England.
Tel: 01684 290243
Fax: 01684 290330
E-mail: sales@gillard.co.uk

DESCRIPTION
Servo Saw Danger Areas

SCALE 1:15
1 of 2

SHEET No


Unless otherwise specified: 0.1mm
Dimensions without tolerances per ISO 2768 - m.K
All Coaxial features concentric within 0.15mm

DRAWING No


A800065

REV SHEET SIZE A3

This drawing is the property of Gillard Cutting Technology & must not be copied or shown to third parties without prior written consent.



Lifting Point
for Forklift



Gillard Cutting Technology
 Alexandra Way
 Ashchurch Business Centre
 Tewkesbury,
 Glos. GL20 8NB
 England.
 Tel: 01684 290243
 Fax: 01684 290330
 E-mail: sales@gillard.co.uk

This drawing is the property of Gillard Cutting Technology & must not be copied or shown to third parties without prior written consent.

DESCRIPTION
 Servo Saw - General Arrangement drawing

SCALE 1:15
 2 of 2

SHEET No

Unless otherwise specified: 0.1mm
 Dimensions without tolerances per ISO 2768 - m.K
 All Coaxial features concentric within 0.15mm

DRAWING No

A800065

REV SHEET SIZE A3